



ROBIN DES BOIS

Country	Port		date	Detention Y/N	Number of deficiencies	
Germany	Hamburg	More detailed inspection	26/10/2018	N	3	
		Category		Deficiency	Defect	Total
		Pollution prevention - MARPOL Annex I		Retention of oil on board	Not as required	1
		Propulsion and auxiliary machinery		Bilge pumping arrangements	Not as required	1
		Propulsion and auxiliary machinery		Gauges,thermometers, etc	Not properly mantained	1
Argentina	Zárate	Follow-up inspection	10/04/2018	N	1	
		Category		Deficiency	Defect	Total
		MARPOL annex V		Garbage record book		1
Germany	Hamburg	More detailed inspection	24/04/2017	N	8	
		Category		Deficiency	Defect	Total
		Certificate & Documentation - Documents		Fire control plan - all	Not as required	1
		Fire safety		Ready availability of fire fighting equipment	Inoperative	1
		ISM		ISM, related deficiencies	Not as required	1
		MLC, 2006 Health protection, medical care, social security		Anchoring devices	Not as required	1
		MLC, 2006 Health protection, medical care, social security		Electrical	Unsafe	1
		MLC, 2006 Health protection, medical care, social security		Winches and capstans	Not properly mantained	1
		Other		Other safety in general	Other	1
		Safety of Navigation		Automatic radar plotting aid (ARPA)	Inoperative	1

Belgium	Antwerp	More detailed inspection	19/01/2017	N 8		
	Category	Deficiency			Defect	Total
	Certificate & Documentation - Documents	Garbage record book			Incorrect	1
	Certificate & Documentation - Documents	Oil record book			Entries missing	1
	Emergency Systems	Emergency source of power - Emergency generator			Not as required (x2)	2
	Fire safety	Fire-dampers			Not as required	1
	ISM	ISM, related deficiencies			Not as required	1
	Pollution prevention - MARPOL Annex I	Oil/oily mixtures from machinery spaces			Lack of familiarity	1
	Safety of Navigation	Automatic radar plotting aid (ARPA)			Inoperative	1

Belgium	Antwerp	Initial inspection	24/02/2016	N 3		
	Category	Deficiency			Defect	Total
	Propulsion and auxiliary machinery	Auxiliary engines			Not as required	1
	Safety of Navigation	Automatic radar plotting aid (ARPA)			Inoperative	1
	Water/Weathertight conditions	Other load lines			Other	1

Germany	Hamburg	More detailed inspection	07/11/2013	N 12		
	Category	Deficiency			Defect	Total
	Emergency Systems	Emergency source of power - Emergency generator			Not as required	1
	Fire safety	Fire pumps			Not as required	1
	Fire safety	Fire-dampers			Inoperative	1
	Fire safety	Ready availability of fire fighting equipment			Missing	1
	Fire safety	Ready availability of fire fighting equipment			Missing	1
	ISM	ISM, related deficiencies			Not as required	1
	Pollution prevention - MARPOL Annex I	15 PPM alarm arrangements			Not as required	1
	Propulsion and auxiliary machinery	Gauges,thermometers, etc			Not as required	1
	Safety of Navigation	Charts			Expired	1
	Structural Conditions	Beams frames floors operational damage			Bent	1
	Structural Conditions	Closing devices watertight doors			Missing	1
	Structural Conditions	Electric equipment in general			Not as required	1

Germany	Hamburg	More detailed inspection	29/08/2013	N 3		
	Category	Deficiency			Defect	Total
	Fire safety	Fire-dampers			Not as required	1
	Propulsion and auxiliary machinery	Auxiliary engines			Not as required	1
	Propulsion and auxiliary machinery	Other propulsion and auxiliary machinery			Other	1

France Dunkirk More detailed inspection 03/10/2012 N 5

Category	Deficiency	Defect	Total
Emergency Systems	Emergency steering position communications/compass	Missing	1
Fire safety	Fixed fire extinguishing installation	Not as required	1
Safety of Navigation	Magnetic compass	Not readable	1
Safety of Navigation	Nautical publications	Missing, Not updated	2

Argentina Zárate Re-inspection 25/08/2011 N 3

Category	Deficiency	Defect	Total
Fire Safety measures	Fire Detection	1	
Propulsion & aux.	Auxiliary Engine	1	
Propulsion & aux.	Other	1	

Argentina La Plata More detailed inspection 21/08/2011 N

Category	Deficiency	Defect	Total
Fire Safety measures	Fire Detection	1	
Maritime Security	Additional measures to enhance maritime security	1	
Propulsion & aux.	Auxiliary Engine	1	
Propulsion & aux.	Other	1	

United Kingdom Tilbury More detailed inspection 20/09/2010 Y 9 35

Category	Deficiency	Defect	Total
Alarm signals	Boiler - alarms	Missing	1
Cargoes	Stowage of cargo	Not as required	1
Fire Safety measures	Doors within main	Not as required (x2)	2
Fire Safety measures	Emergency escape breathing device	Not as required	1
Fire Safety measures	Fire control plan - all	Not as required	1
Fire Safety measures	Fire fighting equipment and appliances	Not as required	1
Fire Safety measures	Fire prevention	Not as required (x3)	3
Fire Safety measures	Jacketed high pressure lines and oil leakage alarm	Not as required	1
Fire Safety measures	Means of control (opening, pumps) Machinery spaces	Not as required (x2)	2
Fire Safety measures	Ready availability of fire fighting equipment	Inoperative, Not properly stowed	2
Fire Safety measures	Ready availability of fire fighting equipment	Not as required	1
Life saving appliances	Lifeboats	Damaged	1
Load lines	Doors	Not properly maintained	1
MARPOL annex V	Other (Marpol annex V)	Other	1

Operational deficiencies	Fire drills	Lack of knowledge	1
Propulsion & aux.	Other propulsion and auxiliary machinery	Other	1
Propulsion & aux.	Propulsion main engine	Not as required	1
Structural Safety	Steering gear	Not as required	1
Working spaces and accident prevention	Electrical	Unsafe	1
Working spaces and accident prevention	Lighting - working spaces	Inoperative	1
Working spaces and accident prevention	Safe means of access	Damaged (x2)	2
Working spaces and accident prevention	Steam pipes and pressure pipes	Unsafe (x2)	2
Working spaces and accident prevention	Ventilation heating working spaces	Not as required	1

category	Deficiency	Defect	Number	Class related deficiency
Alarm signals	Boiler - alarms	Malfunctioning	1	No
ISM related deficiencies	Maintenance of the ship and equipment	Not according SMS	1	No
Life saving appliances	Lifeboats	Damaged	1	No
MARPOL annex I	Suspected of discharge violation	Not as required	1	No
Propulsion & aux.	Cleanliness of engine room	Insufficient	1	No